GFICO

07

FOR SUPPLEMENT REQUEST COPY THE

LINK BELOW

partners.geico.com 1345 Perimeter Pkwy Virginia Beach, VA 23454 Phone: (865) 230-3695

none: (865) 230-3695

Fax: (844) 567-6845 Workfile ID:

Claim #:

boc

Claim #: 0111694830101107-01 rkfile ID: 457386f3

0111694830101107-01

Estimate of Record

Written By: JAMES REEVES, 9/28/2018 4:17:22 PM

Adjuster: Reeves, Clay

Insured: Joshua Scott Owner Policy #: 0126301902

Collision Date of Loss: 09/27/2018 07:00 PM Days to Repair: 1

Point of Impact: 12 Front Deductible: 500.00

Owner (Insured): Inspection Location: Appraiser Information: Repair Facility:

Joshua Scott ATow

Type of Loss:

31 Riverside Dr ATow

Oak Ridge, TN 37830 178 Oak Ridge Tpke (865) 272-9122 Business Oak Ridge, TN 37830

(865) 272-9897 Evening Field

jamreeves@geico.com

(865) 382-3590

VEHICLE

2008 CHEV Corvette Z06 2D CPE 8-7.0L Gasoline SFI yellow

VIN: 1G1YY26E385132638 Production Date: 05/2008 Interior Color: black License: 898rxn Odometer: 35989 Exterior Color: yellow

State: TN Condition:

TRANSMISSION STEERING WHEEL TOUCH AM RADIO FOG LAMPS

CONTROLS

6 SPEED TRANSMISSION CONSOLE/STORAGE FM RADIO XENON HEADLAMPS
DRIVER CONVENIENCE HOME LINK STEREO POWER STEERING
KEYLESS ENTRY INSTRUMENT PANEL SEARCH/SEEK POWER BRAKES

MESSAGE CENTER TRACTION CONTROL CD PLAYER ANTI-LOCK BRAKES (4) MEMORY PACKAGE STABILITY CONTROL CD CHANGER/STACKER **GLASS & MIRRORS** POWER DRIVER SEAT **POSITRACTION AUXILIARY AUDIO CONNECTION DUAL MIRRORS** POWER WINDOWS HEADS UP DISPLAY PREMIUM RADIO TINTED GLASS

POWER LOCKS ALARM SATELLITE RADIO SEATS

POWER MIRRORS AIR CONDITIONING SAFETY LEATHER SEATS
HEATED MIRRORS CLIMATE CONTROL DRIVERS SIDE AIR BAG BUCKET SEATS

POWER TRUNK/GATE RELEASE REAR DEFOGGER PASSENGER AIR BAG POWER PASSENGER SEAT

CRUISE CONTROL HANDS FREE DEVICE FRONT SIDE IMPACT AIR BAGS HEATED SEATS
INTERMITTENT WIPERS COMMUNICATION SYSTEM PAINT WHEELS

TILT WHEEL NAVIGATION SYSTEM CLEARCOAT PAINT 4-WHEEL DISC BRAKES

0111694830101107-01

Workfile ID: 457386f3

Estimate of Record

2008 CHEV Corvette Z06 2D CPE 8-7.0L Gasoline SFI yellow

TELESCOPIC WHEEL RADIO FRONT END CHROME WHEELS

Claim #: Workfile ID: 0111694830101107-01

457386f3

Estimate of Record

2008 CHEV Corvette Z06 2D CPE 8-7.0L Gasoline SFI yellow

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUN	MPER						,
2			O/H front bumper				3.5	
3	<>	Repl	Bumper cover	15915335	1	883.28	Incl.	3.2
4			Add for Clear Coat					1.3
5	**	Repl	A/M Bumper cover clip #1	10139	1	5.60	Incl.	
6	**	Repl	A/M Bumper cover clip #2	P85259	1	3.63	Incl.	
7		Repl	Bumper cover retainer	11609871	1	5.98		
8		Repl	RT Bumper cover reinforcement	10330822	1	11.10	Incl.	
9		Repl	LT Bumper cover reinforcement	10330821	1	10.35	Incl.	
10		Repl	Energy absorber	15789107	1	186.30	Incl.	
11		Repl	Energy absorber spacer	15242109	1	11.19	Incl.	
12	*	Repl	LKQ Impact bar w/o tow hook (ALU) +25%	142166	1	156.25 s	<u>3.5</u>	
13		Repl	Front deflector	21992641	1	134.38	Incl.	
14		Repl	RT Lower deflector	20896058	1	65.58	0.2	
15		Repl	LT Lower deflector	20896057	1	70.30	0.2	
16		Repl	Lower grille	15857168	1	98.35	Incl.	
17		Repl	Upper molding	15801407	1	46.72	0.2	
18	**	Repl	A/M Emblem	10370895-AT	1	45.00	Incl.	
19	FRONT LAN	ЛPS						
20		R&I	LT Headlamp assy yellow	20789681			0.7	
21	*	Rpr	LT Headlamp assy yellow	20789681			<u>0.5</u>	
			NOTE: repair rubber seal. not availa	ble as a separate item				
22	**	Repl	A/M NSF LT Fog lamp assy	GM2592291N	1	112.72	Incl.	
23			Aim fog lamps				0.3	
24		R&I	RT Fog lamp assy	25942592			Incl.	
25		R&I	RT Side marker lamp	10316652			Incl.	
26		R&I	LT Side marker lamp	10316651			Incl.	
27	*	Repl	LKQ RT Headlamp assy yellow +25%	ZDQMOU	1	593.75	<u>0.7</u>	
28			Aim headlamps				0.5	
29	RADIATOR	SUPPORT	Γ					
30		Repl	Skid plate	20939828	1	630.53	1.5	
31	HOOD							
32	*	Rpr	Hood	25805421			<u>3.0</u>	<u>1.6</u>
			NOTE: includes repar to fiber glass	and align hood.				
33			Overlap Major Non-Adj. Panel					-0.2
34			Add for Clear Coat					0.3
35	*	R&I	RT Stop bracket Z06, ZR1 & 427	15294880			0.2	
36		R&I	Insulator	25958874			0.3	
37	*	Repl	LKQ RT Hinge +25%	~185716547	1	50.00	<u>0.4</u>	0.3
38			Add for Clear Coat					0.1

0111694830101107-01

Workfile ID:

457386f3

Estimate of Record

39		Repl	RT Latch	15910868	1	44.07		0.5	
40	FENDER								
41	*	R&I	RT Rear insulator	15288526				<u>0.2</u>	
42	*	Rpr	RT Fender	20814264				<u>1.0</u>	<u>1</u>
43			Overlap Major Adj. Panel						-0
44			Add for Clear Coat						C
45		Repl	RT Wheelhouse	15823164	1	563.48	S	4.5	1
			NOTE: LABOR: Time is after fender a bonding surface, position wheelhous	- ·	noved. Tii	me includes	removii	ng adhesive, pr	epare
46		R&I	RT R&I fender assy	20814264				2.0	
47			Deduct for Overlap					-0.4	
48			Deduct for Overlap					-0.3	
49	*	R&I	RT Emblem "Z06"	15812355				0.2	
50	FRAME								
51	*	Rpr	RT Side rail assy (ALU)	89025164			S	3.0	
		·	NOTE: After pull set up n measure						
52	ELECTRICAL		'						
53	*	R&I	Junction block	25954866				0.3	
54	*	R&I	Engine harness manual trans w/Z06	25908594				<u>0.5</u>	
			NOTE: disconnect clips and move to	gain access to wheelhouse					
55	ENGINE		·	_					
56		R&I	Housing	15839508				0.3	
			NOTE: AIR CLEANER, ATTACHES TO	SHIELD.					
57	*	R&I	Outlet duct clamp front	SEE FOOTNOTE				0.2	
58		R&I	RT Sight shield	12574620				0.2	
59		R&I	LT Sight shield	12574619				0.2	
60	*	R&I	Oil tank	SEE FOOTNOTE				0.3	
			NOTE: ATTACHED TO THE WHEEL H					<u> </u>	
51	WHEELS								
62		R&I	RT R&I wheel	9596909			m	0.1	
			NOTE: FOR BMPR REMOVAL.						
63		R&I	LT R&I wheel	9596909			m	0.1	
00			NOTE: FOR BMPR REMOVAL.	7070707			•••	0	
64		R&I	RT R&I wheel	9596911			m	0.1	
			NOTE: FOR BMPR REMOVAL.						
65		R&I	LT R&I wheel	9596911			m	0.1	
			NOTE: FOR BMPR REMOVAL.	7070711			•••	0	
66	RESTRAINT S	YSTFM							
67	#		Clean and retape		1			0.2	
68		Repl	Driver air bag	25989539	1	765.00	m	0.6	
50		Κυρι	NOTE: FRONT DEPLOYMENT Deployed air bag module(s)	25707337	ı	700.00	***	0.0	

0111694830101107-01

Workfile ID: 457386f3

Estimate of Record

008 CH	HEV Corvette Z06	2D CPE	8-7.0L Gasoline SFI yellow					
			Seat belt pretensioner Diagnostic unit (SDM) Seat belts, in use during collision					
69			Air bag system diagnosis			m	0.5	
70		Repl	LT Belt & retractor black Z06 & ZR1	19151308	1	208.88	1.2	
71		Repl	Diagnostic unit w/side air bag Z06 & ZR1	22740010	1	510.00 m	0.7	
72		Repl	Ft impact sensor Z06 & ZR1	15781091	1	203.98 m	0.6	
73	DOOR							
74	*	Rpr	RT Outer panel NOTE: FOR FRNT EDGE FIBERGALSS.	89023578			<u>1.0</u>	<u>1.5</u>
75			Overlap Major Adj. Panel					-0.4
76			Add for Clear Coat					0.2
77		R&I	RT Mirror outside w/o light sensitive, w/o digital audio	15795838			0.7	
78		R&I	RT Door glass GM	15270577			0.6	
79	*	R&I	RT Window regulator	22895756			0.7	
80	*	R&I	RT Handle switch	22751230			0.2	
81		R&I	RT R&I trim panel	25799652			0.5	
82	QUARTER PAN	IEL						
83		R&I	RT Wheelhouse liner Z06, ZR1, 427 & Grand Sport	15874588			Incl.	
84	*	Rpr	RT Quarter panel coupe Z06 & ZR1	22813553			<u>0.5</u>	<u>1.8</u>
85			Overlap Major Adj. Panel					-0.4
86			Add for Clear Coat					0.3
87	*	R&I	RT Upper insulator	SEE FOOTNOTE			0.2	
88	*	R&I	RT Emblem	15223484			0.2	
89		R&I	RT Wheel opng mldg w/Z06, ZR1, 427 & GS	15818636			0.2	
90	REAR LAMPS							
91		R&I	RT Side marker lamp	10440722			0.3	
92	REAR BUMPER	₹						
93		R&I	R&I bumper cover	15895252			4.0	
94	#		Clean and retape		1		0.2	
95	MISCELLANEC	US OF	PERATIONS					
96	#		COVER CAR		1		0.2	
97	#	Rpr	SET UP & MEASURE				1.5	
98	#	Repl	UNIBODY PULL		1		2.0	
99	#	Subl	FLEX ADDITIVE		1	5.00 T		
100	#	Repl	RESTORE CORROSION LABOR		1		0.2	
101	#	Subl	RESTORE CORROSION PROTECTION		1	10.00 T		
102	#	Subl	4W ALIGNMENT		1	59.95		

0111694830101107-01

Workfile ID:

457386f3

Estimate of Record

2008 CHEV Corvette Z06 2D CPE 8-7.0L Gasoline SFI yellow								
103	# Re	ol Seam seal / panel adhesive		1	35.00			
104	OTHER CHARGES							
105	#	E.P.C.		1	3.00			
•			SUBTOTALS		5,529.37	45.8	11.4	

NOTES

Prior Damage Notes: r/c left mirror, r/c hood front

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				5,511.37
Body Labor	45.8 hrs	@	\$ 44.00 /hr	2,015.20
Paint Labor	11.4 hrs	@	\$ 44.00 /hr	501.60
Paint Supplies	11.4 hrs	@	\$ 34.00 /hr	387.60
Miscellaneous				15.00
Other Charges				3.00
Subtotal				8,433.77
Sales Tax	\$ 8,433.77	@	9.2500 %	780.12
Total Cost of Repairs				9,213.89
Deductible				500.00
Total Adjustments		·		500.00
Net Cost of Repairs	_	·		8,713.89

MyPriceLink Estimate ID: 474934461742481408

0111694830101107-01

Workfile ID: 457386f3

Estimate of Record

2008 CHEV Corvette Z06 2D CPE 8-7.0L Gasoline SFI yellow

This is not an authorization to repair.

All GEICO customers have the right to have their vehicle repaired in the shop of their choice.

No Supplement will be honored unless authorized by GEICO.

NOTICE: Vehicles constructed of special metals may require the use of specialized welding and bonding equipment. Proper measuring and structural repair systems are required on today's vehicle to accurately accomplish vehicle repairs. Make sure your shop has the proper equipment to repair your vehicle.

ALTERNATE PARTS DISCLAIMER:

IF A QUALITY REPLACEMENT PART (A/M, LKQ, RECOND OR OPT OEM) APPEARS ON THIS ESTIMATE, IT INDICATES THAT THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. GUARANTEES, IF ANY, APPLICABLE TO THESE REPLACEMENT CRASH PARTS ARE PROVIDED BY THE PART MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

***IN ADDITION TO ANY SUCH GUARANTEES, GEICO PROVIDES THE FOLLOWING:

****OWNER LIMITED GUARANTEE**** WE GUARANTEE THAT ALL QUALITY REPLACEMENT BODY PARTS (PARTS NOT MANUFACTURED BY THE MANUFACTURER) IDENTIFIED ON YOUR ESTIMATE, ARE FREE OF DEFECTS IN MATERIAL AND WORKMANSHIP AND MEET GENERALLY ACCEPTED INDUSTRY STANDARDS. THIS PARTS AND LABOR GUARANTEE WILL BE IN EFFECT FOR AS LONG AS YOU OWN THE VEHICLE DESCRIBED IN THE ESTIMATE. THIS GUARANTEE COVERS THE COST OF THE PART, LABOR TO INSTALL, AND INCIDENTALS SUCH AS PAINT AND MATERIALS AND IS SPECIFICALLY LIMITED TO THOSE ITEMS. THIS GUARANTEE DOES NOT COVER LOSS OR DAMAGE THAT IS UNRELATED TO DEFECTS IN THE QUALITY REPLACEMENT PARTS. THIS IS NOT TRANSFERABLE. IF ANY QUALITY REPLACEMENT PARTS ARE DEFECTIVE IN EITHER MATERIAL OR WORKMANSHIP, CONTACT YOUR LOCAL GEICO REPRESENTATIVE.

IT IS A CRIME TO KNOWINGLY PROVIDE FALSE, INCOMPLETE OR MISLEADING INFORMATION TO AN INSURANCE COMPANY FOR THE PURPOSE OF DEFRAUDING THE COMPANY. PENALTIES INCLUDE IMPRISONMENT, FINES AND DENIAL OF INSURANCE BENEFITS.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE PARTS MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

0111694830101107-01

Workfile ID: 457386f3

Estimate of Record

2008 CHEV Corvette Z06 2D CPE 8-7.0L Gasoline SFI yellow

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR1CF05, CCC Data Date 9/10/2018, and potentially other third party sources of data; and (b) the parts presented are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2019 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

0111694830101107-01

Workfile ID:

457386f3

Estimate of Record

2008 CHEV Corvette Z06 2D CPE 8-7.0L Gasoline SFI yellow

ALTERNATE PARTS SUPPLIERS

Line	Supplier	Description	Price
5	Kimball Midwest - Columbus OH	#10139	\$ 5.60
	Inside Sales	A/M Bumper cover clip #1	
	4800 Roberts Road		
	Columbus OH 43228		
	(614) 951-2098		
6	Kent Automotive	#P85259	\$ 3.63
	Customer Service	A/M Bumper cover clip #2	
	8770 W. Bryn Mawr		
	Chicago IL 60631		
	(888) 937-5368		
12	Eastern Auto Salvage	#142166	\$ 125.00
	John Bowers	LKQ Impact bar w/o tow hook (ALU) +25%	
	232 Mccaskll Road	BUMPER REINF FRONT-RED - EXC. Z06	
	Biscoe NC 27209		
	(910) 428-9691		
18	Adhesive Templates (Adhesive Only)	#10370895-AT	\$ 45.00
	4717 CAMPUS DR	A/M Emblem	
	KALAMAZOO MI 49008	Quote: 309418274	
	(888) 249-3350	Expires: 10/04/18	
22	Go-Parts (FedEx)	#GM2592291N	\$ 112.72
	1050 CAMBRIDGE SQ STE C	A/M NSF LT Fog lamp assy	
	ALPHARETTA GA 30009	Quote: 333q-8411631-6073	
	(770) 965-6400	Expires: 10/04/18	
27	Autolights	#ZDQMOU	\$ 475.00
	Melanie Field	LKQ RT Headlamp assy yellow +25%	
	950 Hilton Road	RT H/LAMP ASSY-RH, INS QUAL, HID,N,25867782,S#A07178 - BLACK (EXTERIOR COLOR OPT 41U), R.	
	Ferndale MI 48220		
	(248) 291-6324		
37	LKQ Knoxville	#~185716547	\$ 40.00
	3475 North Bend Circle	LKQ RT Hinge +25%	
	Alcoa TN 37701	Hood Hinge R, R.,S#\$J5765	
	(888) 289-2309	Quote: 260058486	
		Expires: 11/11/18	